CMHC SCHL

Helping to house Canadians



Canada

MOISTURE PROBLEMS IN BUILDINGS: A BIBLIOGRAPHY

HUMIDITÉ DANS LES CONSTRUCTIONS: UNE BIBLIOGRAPHIE

Prepared at:

Canadian Housing Information Centre
Canada Mortgage and Housing Corporation
Ground Floor, Annex
Montreal Road
Ottawa, Ontario
K1A 0P7

Préparé au:

Centre canadien de documentation
sur l'habitation
Société canadienne d'hypothèques
et de logement
Rez-de-Chaussée, Annex
Chemin Montréal
Ottawa, Ontario
K1A 0P7

Revised/Revisée
July/juillet 1990

92-07094/

Moisture Problems in Buildings: A Bibliography
Humidité dans les constructions: Une Bibliographie

US1
HD110
81D23

Abendroth, Harry R. A Design Guide for Dry Basements in Existing Homes: Final Report. Prepared for U.S. Department of Housing and Urban Development, Office of Policy Development and Research; prepared by AMAF Industries, Inc. Washington, D.C.: The Office; Springfield, Va.: NTIS, 1981.

SW5
BR20
86D02

Adamson, Bo ... et al. Energy Conservation, Climatic Control and Moisture in Buildings: Research at the Department of Building Science, Lund Institute of Technology, 1980-1985. Document; 1986: D2. Stockholm, Sweden: Swedish Council for Building Research, 1986.

TH
7015
T36
no. 20

Air Infiltration and Ventilation Centre. Airborne Moisture Transfer: New Zealand Workshop, Proceedings and Bibliographic Review. Technical Note AIVC; AIC-TN-20-87. Bracknell, Berkshire: The Centre, 1987.

Ca2
AL
M10
87C51

Alberta. Energy Conservation Branch. Condensation Concerns. ENR Publication ENR 1/17-no. 9. Rev. ed. Edmonton: Alberta Energy, The Branch, 1987.

TH
9031
M54
1990

American Hotel and Motel Association. Research Foundation. Mildew and Moisture Control: Problem Avoidance in New and Existing Hotels and Motels: A Round Table Discussion, Feb. 6, 1990, New Orleans Airport Hilton Hotel, Kenner, Louisiana. Washington, D.C.: The Association, 1990.

US1
D5
74B373

Anderson, L.O. and Sherwood, G.E. Condensation Problems in Your House: Prevention and Solution. Washington, D.C.: U.S. Dept. of Agriculture, Forest Service, 1974.

SW5
BR20
85D06

Andersson, Ann-Charlotte. Verification of Calculation Methods for Moisture Transport in Porous Building Materials. Document D6: 1985. Stockholm, Sweden: Swedish Council for Building Research, 1985.

Cal
MH65
87M57

Appin Associates ... et al. Moisture Source Strength: Measurements in Selected Canadian Cities. Prepared for Project Implementation Division, Policy, Research and Programs Sector, Canada Mortgage and Housing Corporation. Principal consultant: Grant Wichenko. Ottawa: The Division, 1987.

Cal
MH65
84F37

B.E.S.T. Corporation (Balanced Energy Systems Technology Inc.). Field Trials of Test Procedures to Determine Internal Moisture Source Strength. Ottawa: Project Implementation Division, Canada Mortgage and Housing Corporation, 1984.

Bales, Erv and Trechsel, Heinz, eds. Moisture Control in Buildings: Workshop Proceedings, September 25-26, 1984. Sponsored by the Moisture Control in Buildings Research Coordinating Committee. Washington, D.C.: Building Thermal Envelope Coordinating Council, c1985.

Bell, H. Noel. Damp: A Practical Guide to Eliminating Dampness in the Irish Home. Dublin: The Author, 1977.

Cal
MH110
85L57

Benson, G.W. Long-Term Stability of Polyethylene Vapour Barrier Film. Prepared for Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation by Plastecnics; principal consultant: G.W. Benson; project manager, CMHC: A.J. Houston; scientific authority: D.J. Carlsson. Ottawa: Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation, 1985.

US1
HD110
81D24

Booth, Raymond W. A Design Guide for Dry Basements in New Homes: Final Report. Washington, D.C.: U.S. Department of Housing and Urban Development, Office of Policy Development and Research; Springfield, VA.: NTIS, 1981.

Brand, R.G. High-Humidity Buildings in Cold Climates: A Case History. DBR paper no. 934. Ottawa: National Research Council of Canada, Division of Building Research, 1980.

Brundrett, G.W. Criteria for Moisture Control. London, England; Boston: Butterworths, 1990.

Cal MH 86V21 — Buchan, Lawton, Parent Limited. Ventilation Alternatives for Maritime Houses: Final Report. Ottawa: Canada Mortgage and Housing Corporation, 1986.

TA 681 S78 1958 — Building Research Advisory Board. A Study of Effectiveness of Concrete Admixtures in Controlling the Transmission of Moisture Through Slabs-on-Ground. Conducted for the Federal Housing Administration; report edited by William S. Brown. Washington, D.C.: Building Research Institute, 1958.

Building Science Forum of Australia. New South Wales Division. Waterproofing of Buildings: Seminar: Wednesday, 28th June, 1989, at 4.45 p.m., Masonic Centre, cnr. Gouldburn and Castlereagh Streets. Sydney, Australia: The Division, 1989.

Cal MH 81M56 — Burnett, Eric F.P. Moisture Related Problems in Housing in Newfoundland. Ottawa: Canada Mortgage and Housing Corporation, 1981.

Cal MH 87C03 — CMHC/CHBA Builders' Workshops (1987). CMHC CHBA Builders' Workshop: Speaker's Manual. Ottawa: Canada Mortgage and Housing Corporation, 1987.

Cal MH 88C04 — CMHC/CHBA Task Force on Moisture Problems in Atlantic Canada. CMHC/CHBA Joint Task Force on Moisture Problems in Atlantic Canada Final Report. Ottawa: Canada Mortgage and Housing Corporation: Canadian Home Builders' Association, 1988.

Cal PW22 88D40 — Canada. Public Works Canada. Architectural and Engineering Services. Moisture Content Inspections. Building Performance Evaluation Series; D40. Ottawa: Public Works Canada, 1988.

Cal PW22 88D40 — Canada. Travaux publics Canada. Services d'architecture et de génie. Migration de l'humidité. Série sur l'évaluation du rendement; D40. Ottawa: Travaux publics Canada, 1988.

Cal MH 80C53 — Canada Mortgage and Housing Corporation. Condensation in the Home: Where, Why, and What To Do About It = Nature et causes de la condensation dans la maison et mesures préventives. Ottawa: The Corporation, 1980.

Cal
MH
87M51

Canada Mortgage and Housing Corporation. Moisture and Air: Problems and Remedies. Ottawa: Canada Mortgage and Housing Corporation; Canadian Home Builders' Association, 1987.

Cal
MH
87M57

Canada Mortgage and Housing Corporation. Moisture Problems. Builders' Series. Ottawa: CMHC, 1987.

SW5
BR20
80D37

Carlsson, Björn; Elmroth, Arne and Engvall, Per-Ake. Airtightness and Thermal Insulation: Building Design Solutions. Stockholm: Swedish Council for Building Research, 1980.

Castle, Richard William. Damp Walls: The Causes and Methods of Treatment of Dampness in Structures: A Practical Handbook for Those Concerned with the Care and Maintenance of Buildings. 3d ed. London: Technical Press, 1964.

Cal
MH
79S73

Central Mortgage and Housing Corporation. Study for Developing Policy Guidelines re: Funding of Electrically Heated Homes. Ottawa: CMHC, 1979.

S01
SI5
71S20

Chinnery, D.N.W. Keeping High-Rise Buildings Dry. Special Report; BOU20. Pretoria, South Africa: Council for Scientific and Industrial Research, 1971.

Ciz, J.B. Condensation in Structures: State-of-the Art. Report; no. 84-166-K. Toronto: Ontario Hydro, Research Division, 1984.

Ca2
ON
EP80
81H78

Ciz, J.B. and Jones, W.R. Humidity Ventilator: Design and Preliminary Performance Evaluation. Toronto: Ontario Hydro, Research Division, 1981.

TH
9031
C59
1986

Coleman, G.R. Guide to Identification of Dampness in Buildings. Sherborne, Dorset: Remedial Technical Services Ltd., 1986.

TH
9031
C6
1985

Collombet, Raymond. L'humidité des bâtiments anciens: causes et effets, diagnostic, remèdes. Paris: Editions du Moniteur, c1985.

UK2
SC
DV15
84C53

Condensation in Housing: A Report on LA Returns, Survey Results, and Remedial Measures. Edinburgh: Building Directorate, Scottish Development Dept., c1984.

Conference on the Problems of Moisture in Historic Monuments, Rome, 1967 = Colloque sur les problèmes que pose l'humidité dans les monuments anciens, Roma 11-14, X. 1967. Paris: International Council of Monuments and Sites, c1969.

Cal
RC54
80P03

Construction Details for Air Tightness: Record of the DBR Seminar/Workshop, October, November 1977 and January 1978. Proceedings No. 3 of the Division of Building Research. Ottawa: National Research Council of Canada, Division of Building Research, 1980.

Cal
MH
85C56

Construction Principles to Inhibit Moisture Accumulation in Walls of New, Wood-Frame Housing in Atlantic Canada: Advisory Document. Ottawa: Canada Mortgage and Housing Corporation; Canadian Home Builders' Association, 1985.

Cook, John Philip. Construction Sealants and Adhesives. New York: Wiley-Interscience, 1970.

TH
7684
D9C67
1984

Corbett, Robert and Miller, Barbara. Infiltration Control: The Air-Vapor Barrier. Butte, MT: National Center for Appropriate Technology, 1984.

Covington, S.A. and McIntyre, I.S. Moisture Conditions in the Walls of Timber Frame Houses: The Effects of Holes in Vapour Barriers. Aylesbury, Buckinghamshire: Princes Risborough Laboratory, 1986.

Croome, Derek J. and Sherratt, A.F.C., eds. Condensation in Buildings. London: Applied Science Publishers, 1972.

Diamant, R.M.E. The Internal Environment of Dwellings. London: Hutchinson Educational, 1971.

TH
9031
D83
1983

Duell, John and Lawson, Fred. Damp Proof Course Detailing. 2nd ed. London: Architectural Press, 1983.

SW5
BR20
78D10

Elmroth, Arne. Well Insulated Airtight Buildings: Design and Construction. Document: D10: 1978. Stockholm: Swedish Council for Building Research, 1978.

Energy Conservation Contractors Warranty Corporation. Report on the User-Friendliness of the Moisture Assessment Prescriptive Procedure. Prepared for Scanada Consultants Limited and Energy Mines and Resources, Canada. Ottawa: Energy, Mines and Resources Canada, c1989.

Ca2
ON
HO
85P63

Enerplan Consultants Ltd. and Allen-Drerup-White Ltd. Primrose Housing Co-operative Moisture Damage Study. Prepared for Ontario Ministry of Municipal Affairs and Housing, Technical Services Division, Research and Development Section. Toronto: Ontario Ministry of Municipal Affairs and Housing, 1985.

Cal
MS
83A38

Eyre, D. and Jennings, D. Air-Vapour Barriers: A General Perspective and Guidelines for Installation. 4th ed. Ottawa: Energy, Mines and Resources Canada, 1983.

CAL
MS
82A38F

Eyre, D. et Jennings, D. Les membranes d'étanchéité: aperçu général et guide d'installation. 3e éd. Ottawa: Énergie, Mines et Ressources Canada, 1982.

TH
9031
L37
1986

Fairey, Philip ... et al. Latent and Sensible Load Distributions in Conventional and Energy Efficient Residences: Final Report. Prepared by Philip Fairey ... et al., Florida Solar Energy Center for Gas Research Institute. Cape Canaveral: The Center; Springfield, Va.: NTIS, 1986.

Cal
MH
84A76

Ferguson, Simek, Clark, Engineers and Architects. Attic Moisture Control North of 60: Investigation and Comparison of Two Potential Solutions. Prepared for Canada Mortgage and Housing Corporation. Ottawa: The Corporation, 1984.

Forest Products Laboratory (U.S.). Condensation Control in Dwelling Construction. By Forest Products Laboratory, Forest Service, U.S. Department of Agriculture, in collaboration with the Division of Standardized Building Codes and Materials, Office of the Administrator, Housing and Home Finance Agency. Washington: Housing and Home Finance Agency, 1949.

Cal
RC69
85N57

Forgues, Yvan. The Ventilation of Insulated Roofs. Building Practice Note no. 57. Ottawa: National Research Council Canada, Division of Building Research, 1985.

Forgues, Yvan. La ventilation des toitures isolée. Note sur la construction; 57F. Ottawa: Conseil national de recherches du Canada, Division des recherches en bâtiment, 1985.

Cal
MH65
87C57

GE Ground Engineering Ltd. Control of Subsurface Moisture: Report on the Use of Sand-Bentonite Backfill. Prepared for Project Implementation Division, Policy, Research and Programs, Canada Mortgage and Housing Corporation by GE Ground Engineering Ltd.; principal consultant: Paul Kozicki. Ottawa: The Division, 1987.

TH
9031
G38
1986

Gaze, A.I. Hygrothermal Tests on Timber Framed Wall Panels with U-values Less Than 0.3 w/m^2 K. Research Report; 86/5. High Wycombe, Buckinghamshire: Timber Research and Development Association, 1986.

TH
9031
G39
1986

Gaze, A.I. Permeability of Timber and Timber Based Products. Research Report; 86/6. High Wycombe, Buckinghamshire: Timber Research and Development Association, c1986.

TH
9031
G395
1986

Gaze, A.I. and Tuckley, A.J.N. Specification, Testing and Performance of Breather Membranes for Timber Frame Housing. Research Report; 86/7. High Wycombe, Buckinghamshire: Timber Research and Development Association, 1986.

TH
9031
G7
1974

Gratwick, Reginald Thomas. Dampness in Buildings. 2d. ed. London: Crosby Lockwood Staples, 1974.

Great Britain. Interdepartmental Working Party on Condensation and Mould in Buildings. Condensation in Dwellings. London: H.M.S.O., 1970-71.

Cal
MH
88C04f

Groupe de travail de la SCHL et de l'ACCH sur les problèmes relatifs à l'humidité dans les régions de l'Atlantique du Canada. Groupe de travail mixte de la SCHL et de l'ACCH sur les problèmes d'humidité des habitations de la région de l'Atlantique du Canada rapport définitif. Ottawa: Société canadienne d'hypothèques et de logement: Association canadienne des constructeurs d'habitations, 1988.

Cal
RC51
81A34

Handegord, G.O. Air Leakage, Ventilation and Moisture Control in Buildings. Ottawa: National Research Council Canada, Division of Building Research, 1981.

TH
9031
F53

Harrje, D.T. ... et al. Field Measurements of Seasonal Wood Moisture Variations in Residential Attics. S.l.: s.n., 198 .

Haves, Philip. Solar Regenerated Desiccant Dehumidification: Final Report. Report EDF-064. Austin, Tex.: Texas Energy and Natural Resources Advisory Council, Energy Development Fund, 1982.

267
N19

How to Control Moisture in Homes. New York: National Mineral Wool Association, 1953.

SW5
BR20
75D11

Human Responses to Dry, Humidified, and Intermittently Humidified Air: An Experimental Study in Large Office Buildings. Document; D11:1975. By L.O. Anderson et al. Stockholm: Swedish Building Research, 1976.

L'humidité dans le bâtiment: séminaire. Organisé avec la collaboration de l'UNESCO par le Collège international des sciences de la construction à Saint-Rémy-lès-Chevreuse (France), du 23 au 25 novembre 1982. Paris: Conseil international de la langue française, c1984.

Cal
RC54
84P07

Humidity, Condensation and Ventilation in Houses: Proceedings of the Building Science Insight '83, October, November and December 1983. Proceedings no. 7. Ottawa: National Research Council Canada, Division of Building Research, 1984.

Hutcheon, N.B. Fundamental Considerations in the Design of Exterior Walls for Buildings. Technical Report no. 13. Ottawa: Division of Building Research, National Research Council, 1953.

Hyland, Richard W. and Hurley, C. Warren. General Guidelines for the On-Site Calibration of Humidity and Moisture Control Systems in Buildings. Prepared for U.S. Navy. Washington, D.C.: U.S. Dept. of Commerce, National Bureau of Standards: For sale by the Supt. of Docs., U.S.G.P.O., 1983.

Cal
MH65
87P65

IBI Group. Prairie Moisture Problems: Crawl Space Investigations in Norway House, Manitoba. Prepared for Project Implementation Division, Policy, Research and Programs Sector, Canada Mortgage and Housing Corporation by the IBI Group; principal consultant: Harold Katzin. Ottawa: The Division, 1987.

International CIB/RILEM Symposium on Moisture Problems in Buildings (2nd: 1974: Rotterdam, Netherlands) Papers presented at the Second International CIB/RILEM Symposium on Moisture Problems in Buildings. Rotterdam: s.n., 1974. 2 volumes.

TH
9031
I58
1985

An Investigation of Condensation Dampness At Darnley and Development of Survey Methods for Condensation Dampness Investigation. A project sponsored by Glasgow District Council in the Department of Architecture and Building Science, University of Strathclyde; project supervisor: Thomas A. Markus. Glasgow: The Department, 1985.

Investigations into Damp-Proof Construction of Walls. New Delhi: National Buildings Organisation and UN Regional Housing Centre, ECAFE, 1970.

Kerr, Dale D. Annotated Bibliography on the Rain Screen Principle. Bibliography no. 45. Ottawa: National Research Council of Canada, Division of Building Research, 1985.

US1
DE79
81B31

Knab, Lawrence; Mathey, Robert and Jenkins, David. Laboratory Evaluation of Nondestructive Methods to Measure Moisture in Built-up Roofing Systems. NBS Building Science Series; 131. Prepared for Directorate of Engineering and Services, U.S. Air Force. Washington: U.S. Dept. of Commerce, National Bureau of Standards, 1981.

Cal
RC69
85N52

Latta, J.K. The Principles and Dilemmas of Designing Durable House Envelopes for the North. Building Practice Note; no. 52. Ottawa: Division of Building Research, National Research Council of Canada, 1985.

Cal
RC69
85N52f

Latta, J.K. Principes et problèmes relatifs à la conception d'enveloppes de bâtiment durables dans le Nord Canadien. Note d'information sur la construction, no. 52F. Ottawa: Division des recherches en bâtiment, Conseil national de recherches Canada, 1985.

Ca2
AL
MA65
87C55

Lee, Tang G. Condensation in Manufactured Housing. Prepared for Alberta Municipal Affairs, Housing Division, Research and Development Section. Edmonton: Alberta Municipal Affairs, 1987.

TH
9031
M64
1982

Lieff, M. and Trechsel, H.R., eds. Moisture Migration in Buildings: A Symposium. Sponsored by ASTM Committee E-6 on Performance of Building Constructions, Philadelphia, Pa., 6 Oct. 1980. Philadelphia, Pa. (1916 Race St., Philadelphia 19103): ASTM, c1982.

TH
9031
L68
1985

Louvigné, Michel et Peccard, Jean-Paul. Prévention et traitement de l'humidité: techniques et produits. Memento CATED; 38. Paris: Centre d'assistance technique et de documentation: Institut technique du bâtiment et des travaux publics, 1985.

Marsh, Paul. Air and Rain Penetration of Buildings. Lancaster; New York: Construction Press, 1977.

TH
9031
M275

Marsh, Paul. Thermal Insulation and Condensation. Lancaster, Eng.: Construction Press, 1979.

Marshall, Terry. Atlantic Canada Wood Framing Moisture Survey. Ottawa: Canada Mortgage and Housing Corporation, 1990.

Cal
MH110
83M53

Marshall Macklin Monaghan Limited. Moisture Induced Problems in NHA Housing. Prepared for the Research Division, Policy Development and Research Sector of Canada Mortgage and Housing Corporation by Marshall Macklin Monaghan Limited; principal consultants, J.H. VanPoorten, J. Timusk, J. Melchers; CMHC Project Manager, Alvin J. Houston. Ottawa: Canada Mortgage and Housing Corporation, c1983. 3 vols.

TH 9031 T4 — Marshall Macklin Monaghan Limited. Testing and Evaluation of Dehumidification Equipment in NHA Housing: Newfoundland. S.l.: Marshall, Macklin, Monaghan, 1983.

TH 9031 C66 1988 — Merrill, John and Parrott, Kathleen, eds. Condensation and Related Moisture Problems in the Home. Urbana-Champaign: American Association of Housing Educators and Small Homes Council-Building Research Council, University of Illinois at Urbana-Champaign, c1988.

TH 9031 M47 — Merrill, John L. Moisture Problems in the Home. Madison, Wis.: University of Wisconsin-Extension, Cooperative Extension Service, 1986?

Cal MT259 82R01 — Middleton Associates. Energy Conservation and House Basements: A Research Report. Prepared by Middleton Associates, under a sub-contract from the Saskatchewan Research Council. BETT Publication 82.01. Ottawa: Energy, Mines and Resources Canada, 1982.

Cal PW25 79T35 — Mill, Peter A. Thermography: A New Building Science Tool. Ottawa: Public Works Canada, Design and Construction (Technology) Branch; Built Works Directorate, Architecture Division, 1979.

Moisture Control. Don Mills, Ont.: Canadian Consulting Engineer, 1979.

TH 9031 M62 1986 — Moisture in Houses: Control Technology for Designers and Builders. Energy Design Update. Arlington, Mass.: Cutter Information Corporation, c1986.

TH 9031 M65 1985 — Moisture Problems in Residential Construction: Separating Myth from Reality. Sponsored by Washington Energy Extension Service, Oregon State University, Extension Energy Program and Puget Sound Power and Light. Seattle: Washington Energy Extension Service, 1985.

Cal MH110 87D61 — Morrison Hershfield Limited. Drying Characteristics in Outer Walls of Low Rise Residential Housing: Final Report. Prepared for the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation. Ottawa: The Division, 1987.

Mould Growth in Buildings: Proceedings of a joint BRE/Paint Research Association seminar held at the Building Research Establishment Princes Risborough Laboratory on 11 and 12 June 1980. Princes Risborough, England: Princes Risborough Laboratory, 1981.

TH 9031 B3 1978
NAHB Research Foundation. Basement Water Leakage ... Causes, Prevention, and Correction. Rev. ed. Washington: National Association of Home Builders, c1978.

TH 9031 P54 1966
NAHB Research Foundation. A Pilot Study of the Causes, Prevention and Correction of Basement Water Leakage Problems for National Association of Home Builders. Rockville, Md.: The Foundation, 1966.

National Association of Home Builders. Controlling Moisture in Homes. Washington: NAHB, 1987.

US1 EM 83M53
National Center for Appropriate Technology. Moisture and Home Energy Conservation: How to Detect, Solve and Avoid Related Problems. Prepared for U.S. Department of Energy, Assistant Secretary, Conservation and Renewable Energy, Small Scale Technology Branch, Appropriate Technology Program. Washington, D.C.: United States Department of Energy, 1983.

Newman, A.J. Rain Penetration Through Masonry Walls: Diagnosis and Remedial Measures. Report BR 117. Garston, Watford: Building Research Establishment, 1988.

TH 9031 N57 1989
Nisson, J.D. Ned. Moisture Control for Homes: A Primer for Designers and Builders. Energy Design Update. Arlington, Mass.: Cutter Information Corporation, c1989.

Cal MH65 88W55
Oboe Engineering. Wood Moisture Monitoring, Halifax, Nova Scotia: Final Report. Ottawa: Canada Mortgage and Housing Corporation, Project Implementation Division, 1988.

Cal MH65 88W56
Oboe Engineering. Wood Siding Moisture Monitoring, St. John's, Newfoundland: Final Report. Ottawa: Canada Mortgage and Housing Corporation, Project Implementation Division, 1988.

TH
9031
045
1988

Oliver, Alan C. Dampness in Buildings. New York: Nichols Publications, c1988.

Cal
MH110
88D28

Onysko, D.M. and Jones, S.K. Development of Vapour Permeability Data for Waferboard. Prepared for the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation by Forintek Canada Corporation. Ottawa: Canada Mortgage and Housing Corporation, 1988.

TH
9031
077
1987

Orr, Harold. Report Regarding Moisture in Floor Space. Saskatoon: Harold Orr and Associates, 1987.

TH
9031
094
1983

Oxley, T.A. and Gobert E.G. Dampness in Buildings: Diagnosis, Treatment, Instruments. London; Boston: Butterworths, 1983.

SW5
BR20
80D05

Pettersson, Bertil and Axen, Bengt. Thermography: Testing of the Thermal Insulation and Airtightness of Buildings. Document D5: 1980. Stockholm: Swedish Council for Building Research, 1980.

Cal
MH
82P68

Pine, Michael. Problems with Attic Moisture: A Review of Corrective Measures Taken to Eliminate Snow Infiltration and Hoar-Frost Accumulation in the Attics of Northern Homes. Ottawa: Canada Mortgage and Housing Corporation, 1982.

Cal
MH110
81F37

Platts, R.E. Field Survey of Moisture-Troubled Walls in Newfoundland Houses. Prepared for the Technical Research Division of Canada Mortgage and Housing Corporation by Scanada Consultants Limited. Ottawa: CMHC, 1981.

TH
9031
P56
1983

Platts, R.E. Wet Walls in Canadian Houses: Problems, Solutions, Policy. Ottawa: Scanada Consultants Limited, 1983.

Powell, Frank J. and Robinson, Henry E. The Effect of Moisture on the Heat Transfer Performance of Insulated Flat-Roof Constructions. NBS Building Science Series, no. 37. Washington: U.S. National Bureau of Standards; for sale by the Supt. of Docs., U.S. Govt. Print. Off., 1971.

Cal
MH
85C56

Principes de construction visant à prévenir l'accumulation d'humidité dans les murs des nouvelles maisons à ossature de bois des régions de l'Atlantique du Canada: conseils et recommandations. Ottawa: Société canadienne d'hypothèques et de logement; Association canadienne des constructeurs d'habitations, 1985.

Quantities, Symbols and Units for the Description of Heat and Moisture Transfer in Building: Conversion Factors. Publication no. 37. Rotterdam: CIB, c1977.

Cal
RC69
85N54

Quirouette, R.L. The Difference Between a Vapour Barrier and an Air Barrier. Building Practice Note; no. 54. Ottawa: National Research Council Canada, Division of Building Research, 1985.

Cal
RC69
85N54F

Quirouette, R.L. La différence entre un pare-vapeur et un pare-air. Note sur la construction; BPN; 54F. Ottawa: Conseil national de recherches Canada, Institut de recherche en construction, c1985.

RILEM/CIB Symposium on Moisture Problems in Buildings (1965: Helsinki, Finland) Moisture Problems in Buildings: RILEM/CIB Symposium 1965. Helsinki: s.n., 1965.

TH
7684
D9R6
1984

Roussel, Michel. Aération des logements. Paris: Editions Eyrolles, c1984.

Cal
MH110
88D61

Rowan Williams Davies and Irwin Inc. Drying Characteristics in Timber Frame Walls of Low-Rise Residential Housing: Final Report. Submitted to the Research Division, Policy Development and Research Sector, Canada Mortgage and Housing Corporation. Ottawa: The Corporation, 1988.

USI
D
7OM11

Rule, Richard Henry. Making Basements Dry. Home and Garden Bulletin no. 115. Rev. Washington: U.S. Dept. of Agriculture; for sale by the Supt. of Docs., U.S. Govt. Print. Off., 1970.

Cal
MH
87C03F

SCHL/ACCH ateliers des constructeurs (1987) SCHL/ACCH ateliers des constructeurs: guide de l'animateur. Ottawa: Société canadienne d'hypothèques et de logement, 1987.

UKI
EN90
82D15

Sanders, C.H. and Cornish, J.P. Dampness: One Week's Complaints in Five Local Authorities in England and Wales. London: Building Research Establishment: H.M.S.O., 1982.

Cal
MH
84C53

Sawers, John W. Condensation in the Home: Where, Why, and What to do About It. Rev ed. Ottawa: Canada Mortgage and Housing Corporation, 1984.

Cal
MH
84C53

Sawers, John W. Nature et causes de la condensation dans la maison et mesures préventives. Nouvelle révision. Ottawa: Société canadienne d'hypothèques et de logement, 1984.

Scanada Consultants. Avoiding Moisture Problems when Retrofitting Canadian Houses to Conserve Energy: Executive Summary for Report. By Scanada Consultants Limited with A.T. Hansen and Provincial Consultants Limited, SAR Engineering, Marshall Macklin Monaghan Limited. Ottawa: Energy Mines and Resources Canada, 1988, c1989.

Cal
MH110
85C55

Scanada Consultants. Computer Model of the Drying of the Exterior Portion of Wood-Frame Walls: Updated Version. Prepared by Scanada Consultants Limited for Morrison Hershfield Limited. Ottawa: Canada Mortgage and Housing Corporation, 1986.

Cal
MH110
80F34

Scanada Consultants. Field Investigations of Moisture Related Problems in Nova Scotia. Report for the Technical Research Division of Canada Mortgage and Housing Corporation. Ottawa: CMHC, 1980.

Cal
MH110
80F33

Scanada Consultants. Field Investigations of Moisture Related Problems in Prince Edward Island. Prepared for the Technical Research Division of Canada Mortgage and Housing Corporation by Scanada Consultants. Ottawa: CMHC, 1980.

Scanada Consultants. The MAPP, a Moisture Assessment and Prescriptive Procedure: Chapter 5 of the Report Avoiding Moisture Problems when Retrofitting Canadian Houses to Conserve Energy; report for Energy, Mines and Resources Canada by Scanada Consultants Limited with A.T. Hansen and Provincial Consultants Limited, SAR Engineering, Marshall Macklin Monaghan Limited. Ottawa: Energy, Mines and Resources Canada, 1988, c1989.

TH
9031
S28

Scanada Consultants. A Survey of Moisture Problems in the Thermally Upgraded Existing Houses: Report. Prepared by Scanada Consultants Limited; for the Division of Building Research of the National Research Council. Ottawa: Scanada Consultants Limited, 1979.

Cal
RC69
84N49

Scott, D.L. Field Visits to Moisture Troubled Housing in a Maritime Climate. Building Practice Note; no. 49. Ottawa: Division of Building Research, National Research Council Canada, 1984.

Cal
RC64
83N05

Scott, D.L. Seasonal Moisture Variation in Wood Siding and Framing: A Case Study. Building Research Note; no. 205. Ottawa: Division of Building Research, National Research Council Canada, 1983.

Seiffert, Karl. Damp Diffusion and Buildings: Prevention of Damp Diffusion Damage in Buildings Design. Transl. from the German by A.B. Phillips and F.H. Turner. Amsterdam; New York: Elsevier Pub. Co., 1970.

Cal
MH110
87P27

Sheltair Scientific Limited. The Performance of Sealed and Insulated Venting Systems in Combination with High Pressure Oil Burners. Prepared for Research Division, Canada Mortgage and Housing Corporation; study prepared by Sheltair Scientific Limited, Scanada-Sheltair Consortium Incorporated; principal consultant: Sebastian Moffatt. Ottawa: The Division, 1987.

Simmons, H. Leslie. Repairing and Extending Weather Barriers. New York: Van Nostrand Reinhold, c1989.

Smith, Baird M. Dampness in Historic Buildings: Methods of Diagnosis and Treatment: Preliminary Report. Washington, D.C.: U.S. Dept. of the Interior, Heritage Conservation and Recreation Service, Technical Preservation Services Division, 1980.

Smith, Baird M. Moisture Problems in Historic Masonry Walls: Diagnosis and Treatment. Washington, D.C.: U.S. Dept. of the Interior, National Park Service, Preservation Assistance Division: For sale by the Supt. of Docs., U.S.G.P.O., 1984.

Cal
MH
87M51F

Société canadienne d'hypothèques et de logement. L'Air et l'humidité: problèmes et solutions. Ottawa: Société d'hypothèques et de logement; Association canadienne des constructeurs d'habitations, 1987.

Cal
MH
80C53

Société canadienne d'hypothèques et de logement. Natures et causes de la condensation dans la maison et mesures préventives = Condensation in the Home: Where, Why, and What to do About It. Ottawa: La Société, 1980.

Cal
MH
88M57F

Société canadienne d'hypothèques et de logement. Les problèmes d'humidité. 2ième édition. Ottawa: La Société, 1987.

TH
9031
S63
1983

Speidel, Karl. Diffusion et condensation de vapeur d'eau dans le bâtiment: processus physique calcul d'après une nouvelle méthode graphique. Traduit et adapté de l'allemand par Jean-Louis Cauchepin. Paris: PYC édition, 1983.

Strelka, C.S. Indoor Swimming Pools: Humidity Caused Problems and Suggested Solutions. ISRC Facility Subcommittee and National Research Council, Institute for Research in Construction. Toronto: Ontario Ministry of Tourism and Recreation, 1987.

Ca2
SA
RS
85M56
Sulatisky, M.T. Moisture Problems at the Borealis Housing Cooperative. Submitted to the Energy Conservation Division, Department of Public Works and Highways, Government of the N.W.T. SRC Publication no. R-823-2-E-85. Saskatoon: Saskatchewan Research Council, 1985.

Symposium: Moisture-Proofing of Buildings: Proceedings. Pretoria: Council for Scientific and Industrial Research, National Building Research Institute, 1971. 2 volumes.

Symposium on Air Infiltration, Ventilation and Moisture Transfer (1986: Fort Worth, Texas) Symposium on Air Infiltration, Ventilation and Moisture Transfer: Worthington Hotel, Fort Worth, Texas, December 2-4, 1986. Symposium chairman, David Eakin. Washington, D.C.: Building Thermal Envelope Coordinating Council, 1986.

Symposium on Humidity Applications - Commercial, Industrial and Residential (1972: New Orleans, La.). Papers presented at the Symposium on Humidity Applications - Commercial, Industrial and Residential: at the semiannual meeting of the American Society of Heating, Refrigerating and Air-Conditioning Engineers, January 23-27, 1972, New Orleans, Louisiana. New York, NY: American Society of Heating, Refrigerating and Air-Conditioning Engineers, c1973.

Symposium on Humidity Measurement (1968: Columbus, Ohio). Papers presented at the Symposium on Humidity Measurement: at the semiannual meeting of the American Society of Heating, Refrigerating and Air-Conditioning Engineers, February 5-8, 1968, Columbus, Ohio. New York, NY: American Society of Heating, Refrigerating and Air-Conditioning Engineers, c1970.

TH
2235
S95
1967
Symposium on Weathertight Joints for Walls (1967: Oslo, Norway) Weathertight Joints for Walls = Les joints muraux étanches aux intemperies. CIB report; 11. Oslo: Norwegian Building Research Institute, 1968.

Cal
MH305
80R28

TES Limited. A Review of Ventilation Requirements for Residential Buildings in Canada. Prepared for Canada Mortgage and Housing Corporation, Technical Research Division. TES Report No; C289-1. Ottawa: CMHC, 1980.

TH
1101
C354
SP3
1980

Thermal Insulation. CWC Datafile SP-3. Ottawa: Canadian Wood Council, 1980.

Ref.
Z
7144
C76C66
1984

Timber Research and Development Association. Condensation. TRADA Library Bibliography TLB 129. Hughenden Valley, England: TRADA, 1984.

UK1
EN92
78P16

Thorogood, R.P. and Rodwell, D.F.G. Moisture in the Walls of Timber-framed Dwellings. Building Research Establishment Current Paper; CP16/78. Buckinghamshire, Eng.: Building Research Establishment, Dept. of the Environment; Springfield, Va.: National Technical Information Service, 1978.

Trechsel, Heinz R. and Bomberg, Mark, eds. Water Vapor Transmission Through Building Materials and Systems: Mechanisms and Measurement. ASTM Special Technical Publication; no. 1039. Philadelphia, PA: ASTM, c1989.

Cal
MH65
87B11

Unies Limited. Basement Condensation: Field Study of New Homes in Winnipeg. Prepared for Project Implementation Division, Policy, Research and Programs, Canada Mortgage and Housing Corporation by Unies Limited; principal consultant, Cam MacInnes. Ottawa: The Division, 1987.

Cal
MH65
87B12

Unies Limited. Basement Condensation: Field Study of New Homes in Winnipeg: Summary Report. Prepared for Project Implementation Division, Policy, Research and Programs, Canada Mortgage and Housing Corporation by Unies Limited; principal consultant, Cam MacInnes. Ottawa: The Division, 1987.

TH
7225
V35

Van Straaten, J.F. Thermal Performance of Buildings. Elsevier Architectural Science Series. Amsterdam; New York: Elsevier, Pub. Co., 1967.

Ref.
Z
5941
V3
no. 500

Vance, Mary. Dampness in Buildings: A Bibliography. Architecture Series: Bibliography; A-500. Monticello, Ill.: Vance Bibliographies, 1981.

Ref.
Z
5941
V3
no. 1591

Vance, Mary. Dampness in Buildings: A Revision of A 500. Architecture Series: Bibliography; A-1591. Monticello, Ill.: Vance Bibliographies, 1986.

USl
HD
79P61

Verrall, Arthur F. and Amburgey, Terry L. Prevention and Control of Decay in Homes. Washington: Department of Housing and Urban Development, 1979.

Voluntary Test Method for Condensation Resistance of Windows, Doors and Glazed Wall Sections. Chicago, Ill.: Architectural Aluminum Manufacturers Association, 1981.

TH
9031
W37

Water Penetration in Buildings: A Research Study and Recommendations for Solution. [S.l.: s.n., 197?].

Weather Proofing: Seminar, Wednesday, July 16, 1986 at 4:45 p.m., Masonic Centre, Castlereagh Street, Sydney. Sydney: Building Science Forum of Australia, New South Wales Division, 1986.

Weatherproofing Existing Buildings: Seminar: Wednesday, April 17, 1985 at 4:45 p.m., Masonic Centre, Castlereagh Street, Sydney. Sydney: Building Science Forum of Australia, New South Wales Division, 1985.

White, Jim H. Moisture Transport in Walls: Canadian Experience. Authorized reprint from Standard Technical Publication 1039. Philadelphia, P.A.: American Society for Testing and Materials, 1989.

Cal
MH110
84S76

White, Jim H. A Summary of Questions Asked at NRC's Building Science Insight '83: "Humidity, Condensation and Ventilation in Houses". Prepared by J.H. White of Canada Mortgage and Housing Corporation, Research Division, as a service to the National Research Council of Canada, Division of Building Research. Ottawa: Canada Mortgage and Housing Corporation, 1984.

CAL
MH
84V23

White, Jim H. Ventilation for Humidity Control: A Research Report. Ottawa: Canada Mortgage and Housing Corp., 1984.

TH
9031
W48
1983

Whiting, D. Assessment of Potential Techniques for In-situ, Real Time Moisture Measurements in Building Envelope Systems - A Literature Survey: Report. Prepared by Construction Technology Laboratories ... for Building Thermal Envelope Systems and Materials, Oak Ridge National Laboratory. Skokie, Ill.: Construction Technology Laboratories: available from the National Technical Information Service, U.S. Department of Commerce, 1983?

US1
DE70
40R63

Woolley, Harold W. Moisture Condensation in Building Walls. Washington, D.C.: U.S. Dept. of Commerce, National Bureau of Standards, 1940; Springfield, Va.: National Technical Information Service, 1973.